	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
П	BRS	72670	maeda		2004/06/14 09:27		
2	BRS	Ŋ	maeda and drawbar	USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/06/14 09:29		
<u>د</u>	BRS	174	maeda and circle	M_TDB	2004/06/14 :09:29		
4	BRS	4	maeda.in. and grader	EPO; JPO; 2004/ DERWENT; IBM_TDB 09:30	2004/06/14 09:30		
Ŋ	BRS	1472	kenichi and maeda	USPAT; EPO; JPO; 2004/06/14 DERWENT; IBM_TDB 09:50	2004/06/14 09:50		
و	BRS	39	kenichi and maeda and circle	USPAT; EPO; JPO; 2004/06/14 DERWENT; IBM_TDB 10:21	2004/06/14 10:21		
7	BRS	2	4084644.pn.	USPAT; EPO; JPO; 2004/06/14 DERWENT; IBM_TDB 10:22	2004/06/14 10:22		
ω	BRS	0	(circle adj gear) and bolt and drawbar and (guide adj shoe) and spigot	and USPAT; US-PGPUB; 2004/06/14 EPO; JPO; DERWENT; IBM_TDB 10:23	2004/06/14 10:23		
_ o	BRS	П	(circle adj gear) and bolt and drawbar and (guide adj shoe)		2004/06/14 10:23		
10	BRS	œ	(circle adj gear) and bolt and drawbar	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/14 12:10		
11	BRS		5667020.pn.	USPAT	2004/06/14 10:25		

en de la companya de la co